



## **Resurface Turnpike (MP: 32.2-38.7 SB and 33.2 to 40.15 NB)**

**FPID: 431100-1, -2**

**March 2015**

---

### **Description:**

This project provided pavement repairs on the Turnpike/SR 821 from MP 32.2 to MP 38.7 (Southbound) and from MP 33.2 to MP 40.15 (Northbound). This project is in preparation for the major widening project through this section (FPID: 435542-1)

### **Benefits:**

- Restores section of the roadway to good pavement condition and increases the overall service life of the roadway.

### **Status:**

This project is scheduled to begin in FY 2016.

### **Investment:**

This project has been funded for a total of 1.7 million by FDOT, Florida's Turnpike Enterprise.

# Resurface Turnpike (MP: 32.2-38.7 SB and 33.2 to 40.15 NB)

FPID: 431100-1, -2

March 2015

